



Staff Meeting: November 27, 2007 08:30-11:30 AM

Location: Kennewick Office

**Attendees:** Don Warf, Alan Brower, Darren Chase, Troy Humphrey & Scott Livingston & Jenn Nighbor

**Recorded by:** Jenn Nighbor

---

**Site Review:**

- **(GRA) Lower Granite Adult** – Running.  
Out of tune, firing timer tags, still getting fish. GMCs next week.
- **(GRJ) Lower Granite Juvenile** – Down.  
Troy and Jim to move sensors. Will involve cutting and welding.  
 Troy to email Jim to set up time to move sensors.
- **(GOJ) Little Goose** – Down.
- **(LMJ) Lower Monumental** – Down. Full Flow still up.
- **(ICH) Ice Harbor Dam** – Dead timer tag or transceiver (A3). Alan believes it is just out of tune.  
Troy – Back panels are in. Putting in level sensors, will be able to know when up or down. Troy's been testing to ensure there is no COE radio transmission interference.  
 Goal is to cover all ladder. 1 per season as gear is pretty expensive.
- **(MC2) – McNary Oregon Shore** – Counting issues due to noise. Won't really know anything until de-watered. Happened about half way through this year.
- **(MC2) – McNary Washington Shore** – # 09 is dead below the water and died around the 16<sup>th</sup>. Will have to wait until ladder is de-watered. Will have a 44 day outage.  
 Darren – verify we have a spare.  
 Need to repair latch on counting window. Bottom latch flipped around and doesn't latch.  
 Darren - Latches on transceivers need to be replaced.
- **(MCJ) – McNary Juvenile** – 84 in event log having issues.  
 Need to put in a sync cable.
- **(JDJ) John Day Juvenile** – Troy heading there probably tomorrow. Having analog comms problems.  
Tune up 01 – 04 or shut them down.  
 Troy to tune up 01 – 04, rough tune.

- **(PRO) Prosser Chandler Diversion Dam** – Troy there today to meet with Embark.  
Adult antennas – haven't seen any problems. Firing good until the 21<sup>st</sup>.  
Sketchy phone issues – phone works on a hit and miss basis.  
Water up Juvenile – usually mid-December. October 15<sup>th</sup> the canal went down.
- **Roza** – Down 1 transceiver. Put in power conditioning.  
1<sup>st</sup> cabinet ¼” of ice in bottom of cabinet UPSs. Cover leaking?  
Icicles on antennas hanging down and hazard to fish.  
Need phone in.
- **(RCX) Rattlesnake Creek** –
- **(BO1) Bradford Island – Bonneville** – Tuning problems.
- **(BO2) Cascades Islands – Bonneville** –
- **(BO3) Washington Ladder – Bonneville** –
- **(BO4) Washington Shore Fishway – Bonneville** – Tuning problems.
- **(B2J) PH2 Juvenile Fish Facility – Bonneville** – Down. Bradford and Cascade will water down.  
Power rerouted – Alan has pics on SMOLT.
- **(BCC) PH2 Corner Collector – Bonneville** –Software issues.
- **(CFJ) Clark Flat Acclimation Pond** –
- **(JCJ) Jack Creek Acclimation Pond** –

**Other News:**

- **MiniMon** – start deleting files on all GMCs. Annually not every GMC. Take a closer look to verify there isn't any files to be needed.  
 January of every year – in SOP (Scott)

**Winter Work:** Reviewed Winter Work list Darren provided for any additions to the list.

Meeting adjourned at 10:30 AM to begin Safety Meeting.